



Response Date:20/05/2024

2024/419 - Collision Data

In response to your recent request for information regarding;

Please can we have personal injury traffic collision data for the period 1st March 2015 to the 1st March 2020, as well as any data you may hold after September 2021.

Please could we have the data for the area shown in the attached plan (LL13 8DE).

Please could we have as much of the following data as is possible:

- **Plot of accident locations** ·
- **Date and time**
- **Weather and Lighting Conditions** ·
- **Number and type of vehicles involved** ·
- **Severity (Slight, Serious, Fatal) - (we only need injury accidents)** ·
- **An OS Grid reference** ·
- **Brief Description of what occurred** ·
- **And anything else you feel relevant**

DATE	TIME	EASTING	NORTHING	SEVERITY	ROAD_COND	VISIBILITY	CASUALTIES	VEHICLES	WEATHER	ACC_DESC
Dec-15	1530	333848	350433	Slight	Wet/Damp	Daylight street lights present	1 slight	Goods vehicle over 3.5 tonnes mgw and under 7.5 tonnes mgw	Fine without high winds	Cas 1 has been waved across by a stationary vehicle in lane one closest to them, however, the cas has ran out into the side of veh 1 in lane 2.
Mar-17	1800	333858	350447	Slight	Dry	Daylight street lights present	1 slight	2 cars	Fine without high winds	2 vehicles have entered onto the roundabout from holt road. Veh 1 inside lane, veh 2 outside lane. Veh 2 intending to go straight onto holt street. Veh 1 nearside collided with veh 2 offside
Oct-19	1117	333940	350554	Slight	Dry	Daylight street lights present	2 slight	2 cars	Fine without high winds	As v1 came off the tesco roundabout down holt road, v1 has veered slightly onto v2's side of the road and caused a front offside collision at an approximate speed of 30mph causing significant damage and an airbag deployment of both vehicles.
Sep-21	228	333861	350449	Slight	Wet/Damp	Darkness: Street lights present and lit	3 slight	Car	Fine without high winds	This is a 1 vehicle rtc whereby three persons on board had minor injuries from seatbelts and airbags. The collision was caused by the road surface becoming slippery with change of weather,

										causing the vehicle to skid and the driver was unable to rectify this. No street furniture was damaged.
--	--	--	--	--	--	--	--	--	--	---

THIS INFORMATION HAS BEEN PROVIDED IN RESPONSE TO A REQUEST
UNDER THE FREEDOM OF INFORMATION ACT 2000, AND IS CORRECT AS AT 17/05/2024